

Duration : Dec 2009-2010

Description :

3.0km of 17.km has shown severe Pavement Failure. MPW appointed CHSS to study the cause of the failure.

Service

Review of project designs, specifications and implementation process. Carry out field tests, inquiries or additional measurements to verify the status of work performed and compliance with specifications Identify the causes of defects and the responsibilities of various parties involved in the process.

